




BatchMagic 2001 HID (keyboard) mode and VCP (serial) mode settings.

Use the BatchMagic as a USB keyboard



Use the BatchMagic with SerialMagic



To send batch data from the BatchMagic 2001 while using HID mode, simply connect the scanner to the USB port, wait for a beep, and press the scan button to send the data to the cursor location of the computer.

BatchMagic 2001 firmware RBB36403 is required for USB-HID